



Lead Paint Risk Assessor Experience

What You Need to Know

To obtain an accreditation as a Maryland Lead Paint Risk Assessor an individual is required to have certain experience to qualify. In addition to training and passing a Lead Paint Risk Assessor Third Party Exam. This information is to be submitted with your application as directed on the application. The experience requirements can be found in the Code of Maryland 26.16.01.16C.

Accredited for One Year

Have been an accredited/licensed Lead Paint Inspector Technician for at least one year.

- This information is to be completed on your Risk Assessor application in the spaces provided.
- If your experience is from another state be sure to enclose a copy of your Inspector Technician or Risk Assessor license from that state with your application for accreditation.

List of Inspection Experience

Complete a list of 20 different inspections that you conducted while appropriately accredited. The inspections are to be from **separate** residential units, public buildings, or commercial properties.

- If you have the experience as describe below, then create a list including the following information: The list is to be submitted with your application for accreditation.

One of the following shall be satisfied:

- List 20 different lead-based inspections
- List 5 different lead-based inspections **and** List 15 different dust inspections
- For each inspection list: number 1-20, date of inspection, address and inspection type (specify XRF, paint chip or dust wipe).
- There are two types of inspection. Inspection types are either: lead-based paint inspection: X-Ray Florescent Analyzer (XRF), paint chip) or dust inspection: dust wipe.

Questions

If you have any questions you may contact the Lead Poisoning Prevention Program at: 410-537-3825.